

Causes of indefinite faults in Estonian 110 kV overhead power grid

Taklaja, Paul; Oidram, Rein; Niitsoo, Jaan; Palu, Ivo Oil shale 2013 / p. 225-243 : ill https://artiklid.elnet.ee/record=b2631741*est

Main bird excrement contamination type causing insulator flashovers in 110 kV overhead power lines in Estonia

Taklaja, Paul; Oidram, Rein; Niitsoo, Jaan; Palu, Ivo Oil shale 2013 / p. 211-224 : ill https://artiklid.elnet.ee/record=b2631738*est

110 kV õhuliinide isolatsiooni töökindluse analüüs ja töökindluse tõstmise meetodid = The study of 110 kV power grid reliability and the measures to decrease insulation failure

Taklaja, Paul 2012 http://www.ester.ee/record=b2857612*est