An analysis of the reasons of the failure of the locking devices of M/V ESTONIA

Ingerma, August; **Strižak, Viktor** Final report on the MV ESTONIA disaster of 28 September 1994. Supplements. Part 2 1997 / Supplement No. 510, 9 p

The strength studies for the locking devices of the bow visor of M/V ESTONIA

Ingerma, August; **Strižak, Viktor** Final report on the MV ESTONIA disaster of 28 September 1994. Supplements. Part 2 1997 / Supplement No. 507, 36 p