

**Biodeterioration, salt distribution and damage to plaster and render/extent and reasons for salt, mould and rot damage**

**Kallavus, Urve** The Final Research Report of the project "Sustainable Management of Historic Rural Churches in the Baltic Sea Region (SMC)" 2013 / p. 57-66 : ill

**Eesti uuritud kirikute ehitustehniline seisund**

**Klõšeiko, Paul; Kalamees, Targo** The Final Research Report of the project "Sustainable Management of Historic Rural Churches in the Baltic Sea Region (SMC)" 2013 / lk. 7-29 : ill

**Energy and indoor climate performance of heat pumps and dehumidification**

Napp, Margus; **Kalamees, Targo** The Final Research Report of the project "Sustainable Management of Historic Rural Churches in the Baltic Sea Region (SMC)" 2013 / p. 102-125

**Indoor climate in a naturally ventilated unheated medieval churches**

**Kalamees, Targo**; Väli, Alan; **Kurik, Lembit** The Final Research Report of the project "Sustainable Management of Historic Rural Churches in the Baltic Sea Region (SMC)" 2013 / p. 30-51 : ill

**Laboratory study of plaster, render and mortar samples**

**Raado, Lembi-Merike; Hain, Tiina** The Final Research Report of the project "Sustainable Management of Historic Rural Churches in the Baltic Sea Region (SMC)" 2013 / p. 69-78 : ill

**Overview of air infiltration in the studied church buildings**

Väli, Alan; **Kalamees, Targo** The Final Research Report of the project "Sustainable Management of Historic Rural Churches in the Baltic Sea Region (SMC)" 2013 / p. 52-56 : ill

**Researching moisture content in the massive limestone walls of medieval churches with the use of microwave sensors**

**Kurik, Lembit** The Final Research Report of the project "Sustainable Management of Historic Rural Churches in the Baltic Sea Region (SMC)" 2013 / p. 79-101 : ill